



Systems

SMART 6

Equipment

CEM Square Glass Fiber Pads

SMART 6 Settings

Calculation Mode	Option	Display Mode
Moisture/Solids	Standard	Moisture

SMART 6 Categories

Ramp Time (sec)	Delta Weight (mg)	Delta Time (sec)
60	5	20

Am. Fan Speed (%)	Run Fan Speed (%)	Run Fan Off (sec)	Weight Comp. (On /Off)
20	50	30	On

Parameters

Stage	Mag (%)	IR (%)	Time (mm:ss)	Max Temp (°C)	Mode
1	10	100	3:00	160	Set Time

Sample Preparation

Procedure

Spread Technique